

FIG. 1

PRIOR ART




FIG. 2

PRIOR ART




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E





FIG. 9F






FIG. 10




FIG. 11A




FIG. 11B

Implant
damaged
layer 60

Damage-
free Ge




FIG. 12